



LIBERTY
OUTDOORS

SERVICE BULLETIN
#LO-005

RE: Black Tank Plumbing

OVERVIEW: This Service Bulletin covers the inspection and potential securing of the black tank plumbing

MODELS: Little Guy Max & Little Guy Mini Max.

PROBLEM: The ABS tube which connects the exterior (undercarriage) black tank plumbing to the bottom of the black water holding tank could possibly come loose which can result in black water releasing into the interior of the trailer when the toilet is flushed.

CORRECTION: Apply ABS cement at the connection point where the ABS pieces meet together to connect the internal black tank plumbing to the exterior (undercarriage) black tank plumbing.

WHAT TO USE: ABS cement.

SUMMARY: The issue does not appear to be widespread but has happened a few times.
The possible affected VIN range of Max and Mini Max trailers is 566006-566609 and 000001-000769
Call your local Liberty Outdoors dealer to arrange an appointment to have your trailer inspected.

NOTE: See picture on page 2, the picture represents the location which needs ABS cement

Please contact us with any questions, concerns or comments:

Warranty Line: 814-444-6679

- warranty@golibertyoutdoors.com
- parts@golibertyoutdoors.com

Technical Service: 814-485-2977

- ts@golibertyoutdoors.com

Factory Main Line: 814-444-1001

Corporate Sales Office: 877-545-4897

- support@golibertyoutdoors.com

Sincerely,

Liberty Outdoors, LLC



LIBERTY
OUTDOORS



A view from under the trailer right below the shower platform, this is the black tank drain and these are the two pieces that need glued together.