



SERVICE BULLETIN
#LO-007

RE: Mini Max Refrigerator Baffle

OVERVIEW: This Service Bulletin covers the inspection and potential securing of the baffle behind the fridge.

MODELS: Little Guy Mini Max.

PROBLEM: It is possible for the fasteners to fail and the baffle will fall behind the fridge. This is dangerous due to the wood baffle potentially falling close to the fridges boiler tube which can get hot when the fridge is operating.

CORRECTION: The baffle can be secured again to the fridge cabinet

WHAT TO USE:

SUMMARY: The issue does not appear to be widespread but has the potential to occur on Mini Max trailers in the VIN range 000001-000337

NOTE: See picture on page 2

Please contact us with any questions, concerns or comments:

Warranty Line: 814-444-6679

- warranty@golibertyoutdoors.com
- parts@golibertyoutdoors.com

Technical Service: 814-485-2977

- ts@golibertyoutdoors.com

Factory Main Line: 814-444-1001

Corporate Sales Office: 877-545-4897

- support@golibertyoutdoors.com

Sincerely,

Liberty Outdoors, LLC



LIBERTY
OUTDOORS



Baffle has broken and fallen down to the bottom of the fridge cabinet